
CHRRENT/VOLTAGE/POWER MONITORING WIRING DIAGRAM WINIECTION LIST 415/20 GELDYER



ConnectionList INA219-3 GND BK LM298 BK LER BUSH 1 NA219-3 -LM298 R BATT 3K 1NA219-3 6ND BATT R INA219-3 GND INA219-4 GND INAZA-IGND INA219-4 640 INA219-1 640 NA219-2 6-ND RERECK KK PNA219-3+ INA29-27 INA 219-1 + INA219-2 + INA 219-1 - UNO +5VIN INA 219-2 - RPID +5VIN VMA 219-2 6 ND KOID G-IN

WIRELESS VONT WIRELESS GND IN 4219-4 -IN 4219-4 GND INA219-1 INAZIG-4 + R INAZIG-4 CND BK BATT CHG VIN R BATT CHG GND BK 4 WITE CONNECTOR TO UNO SU, Cr, SCL, SDA