Some addional infos wanted

The details of the hardware are <u>here</u>. <u>vaxinf</u> **New Member** Essentially, I've got a Itanium workstation (HP zx2000), and a dual-core Montecito. Electrically, they should work together (since there are essentially identical systems that do support Montecito CPUs), but HP discontinued firmware updates for the zx2000 when they dumped their workstation line, and this was prior to Montecito's release. Jun 24, 2012 Joined: Messages: Click to expand. I know it a long time since your first posting but I try to solve a similar problem with a IA64 firmware (rx4640).

Could you contact me please via email: information (at) dvdwrite.de thanx

Eberhard (You must log in or sign up to reply here.)

These are the coziest shoes I've ever put on - Last Day 70% Off! Orthowalkway

Modding

Sign Up to see what your friends like.

Specific Hardware Topics

Share This Page

Forums

Home

oupimiquo said: 1

vB 3.x - Fluid Contact Us Help Home Top 🔊 Terms and Rules Privacy Policy

OPEN

Advertisement:

Forum software by XenForo™ © 2010-2018 XenForo Ltd. Quality Add-Ons by WMTech © 2022 WebMachine Technologies, Inc.

Modding Worklogs

micron21