



Zendure / zenSDK ▾



Code

Issues 29

Pull requests 2

Discussions

Actions

Projects

Security and quality

Insights

New issue



API call limitations #5

Closed



thehawkes opened on Apr 4, 2025



Aloha,

first of all, thank you for that RestAPI ;)

Atm I am doing some Rest Calls via HomeAssistant to set `outputLimit` , `inputLimit` and `acMode` depending on current home power consumption.

I've set the change limit to:

- `outputLimit` and `inputLimit` once every minute
- `acMode` every 3 mins max

Are there any limitations on the zenSDK or HW side how often these settings can be changed without issues?

I would like to lower the change interval for the `limit` to every 30s or even lower, to help with peaks due to clouds etc.

Regards



dav1dBoy on Apr 7, 2025

Member



Aloha,

Closed

API call limitations #5



depending on current home power consumption.

I've set the change limit to:

- `outputLimit` and `inputLimit` once every minute
- `acMode` every 3 mins max

Are there any limitations on the zenSDK or HW side how often these settings can be changed without issues?

I would like to lower the change interval for the `limit` to every 30s or even lower, to help with peaks due to clouds etc.

Regards

Hi

Thanks a lot for your feedback and for using the REST API via HomeAssistant — really cool to hear you're actively integrating it with dynamic power management!

Regarding your question about the update frequency of `outputLimit`, `inputLimit`, and `acMode`:
The current firmware and ZenSDK do not enforce hard limits on how often these properties can be updated, but for system stability and to avoid unnecessary wear or CPU load, we suggest the following recommended minimum intervals:

- `outputLimit` / `inputLimit`: every 10 seconds (or longer)
- `acMode`: every 30 seconds to 1 minute

So yes — lowering your update interval to every 30s or even every 10s for power limits is acceptable and well within the expected design range. Just make sure the control logic avoids unnecessary repeated writes if the values haven't changed significantly (to reduce bus load and EEPROM writes).

Let me know if you encounter any instability or have more integration ideas — happy to support!



 **dav1dBoy** closed this as completed on Apr 7, 2025

Add a comment

Write

Preview

H B I       @   

Use Markdown to format your comment

 Paste, drop, or click to add files

 Reopen issue

Comment

Metadata

Assignees

No one assigned

Labels

No labels

Type

No type

Projects

No projects

Milestone

No milestone

Relationships

None yet