

P1.0 · where the sensing elements go
Section through the soft insert; original hard frame shown as an outline
CH2
front / back
CH3
front / back
CH4
front / back
CH5
front / back
CH0 + CH1
Two thin nail prongs
0.4 mm nominal addition
Original hard-frame outline
Front air channel → B high
Back air channel → A low
Native Z (mm)
Native Y (mm; nail at left)
40
30
20
10
0
−120
−100
−80
−60
−40
−20
0