F1 cable inspection pose · native pin correspondence

Illustration is not the installed cable route; solder-land transverse order represents contact order.