f1_ch3_columns_fit

FIT PATTERN ONLY · NO COPPER ARTWORK · PRINT AT 100%

CH3 columns → J3C · view from F.Cu side



50 mm scale bar · verify with a ruler

Dashed lines bound the 90° bend. Form around the radius; do not crease.

Connector datum, source join, bending slack and physical fit remain unverified.