

Firmware Update history

[Feb 9, 2026]

2.2.4 - Fixed the intermittent unresponsive mix control.

[Jan 22, 2026]

2.2.3 - Fixed the intermittent lock up issue when adjusting the mix setting for a single channel.
- Fixed the lack of display update when adjusting only the R channel mix setting.

[Sep 3, 2025]

2.2.2 - Fixed lock up issue when saving a preset after turning off modulation LFO.

[July 31, 2025]

2.2.1 - Fixed a bug with the Dry/Mix control.

[June 2, 2025]

2.2.0 - Added 'Wet Level' as an expression-assignable parameter.

[May 21, 2025]

2.1.0 - Added a Exp/Aux select function in Global setting menu.

[Jul 29, 2024]

2.0.4 - Fixed an issue with mixing control.

[Feb 19, 2024]

2.0.3 - Fixed an issue with bypass/engage operation.
- Fixed a bug in global tempo operation.

[Feb 5, 2024]

2.0.2 - Fixed a bug in "cc_Dry()" function.
- Fixed freezing issues in series routing mode.

[Jan 10, 2024]

2.0.1 - Fixed freezing issue in firmware 2.0.0.

[Jan 8, 2024]

2.0.0 - Added Global Dry signal On/Off feature.
- Added two subdivision values: Whole-2 and Whole-4.
- Added Random LFO shape.
- Added two MIDI CC functions: Wet-L (CC#37) and Wet-R (CC#38).

[Sep 18, 2023]

1.0.8 - Fixed bug in the blending operation.

[June 27, 2023]

1.0.7 - Improved operational stability.

[June 18, 2023]

1.0.6 - Fixed a bug with Midi CC#19 operation.

[June 1, 2023]

1.0.4 - Added 'Gain X' and "Gain Y" functions to Midi CC implementation.

1.0.5 - Added 'Mute L', 'Mute R', and 'Mute LR' functions to Midi CC implementation.

[May 19, 2023]

1.0.3 - Improved encoder operation accuracy and robustness.

[May 11, 2023]

1.0.2 - Fixed a bug in LFO state toggling routine, which could cause system error when midi clock is reception is active.

[Mar 31, 2023]

1.0.1 - Fixed potential unintended behaviors when exiting Globals/Options menu.

[Nov 21, 2022]

1.0.0 - First release firmware.