

Scan Report

September 19, 2026

Summary

This document reports on the results of an automatic security scan. All dates are displayed using the timezone “Coordinated Universal Time”, which is abbreviated “UTC”. The task was “Scan Linksys WRT54GL”. The scan started at Sat Sep 19 11:18:59 2026 UTC and ended at Sat Sep 19 12:20:33 2026 UTC. The report first summarises the results found. Then, for each host, the report describes every issue found. Please consider the advice given in each description, in order to rectify the issue.

Contents

1	Result Overview	2
2	Results per Host	2
2.1	192.168.1.250	2
2.1.1	Critical 80/tcp	2
2.1.2	Medium 80/tcp	3
2.1.3	Low general/icmp	3

1 Result Overview

Host	Critical	High	Medium	Low	Log	False P.
192.168.1.250	1	0	1	1	0	0
Total: 1	1	0	1	1	0	0

Vendor security updates are not trusted.

Overrides are off. Even when a result has an override, this report uses the actual threat of the result.

Information on overrides is included in the report.

Notes are included in the report.

This report might not show details of all issues that were found.

Issues with the threat level “Log” are not shown.

Issues with the threat level “Debug” are not shown.

Issues with the threat level “False Positive” are not shown.

Only results with a minimum QoD of 70 are shown.

This report contains all 3 results selected by the filtering described above. Before filtering there were 20 results.

2 Results per Host

2.1 192.168.1.250

Host scan start Sat Sep 19 11:19:12 2026 UTC
Host scan end Sat Sep 19 12:20:26 2026 UTC

Service (Port)	Threat Level
80/tcp	Critical
80/tcp	Medium
general/icmp	Low

2.1.1 Critical 80/tcp

Critical (CVSS: 9.8)
NVT: HTTP Brute Force Logins With Default Credentials Reporting
Summary It was possible to login into the remote Web Application using default credentials.
Quality of Detection (QoD): 95%
Vulnerability Detection Result It was possible to login with the following credentials (<URL>:<User>:<Password> ⇔:<HTTP status code>) http://192.168.1.250/:Administrator:admin:HTTP/1.0 200 Ok http://192.168.1.250/:admin:admin:HTTP/1.0 200 Ok http://192.168.1.250/:login:admin:HTTP/1.0 200 Ok http://192.168.1.250/:manager:admin:HTTP/1.0 200 Ok http://192.168.1.250/:root:admin:HTTP/1.0 200 Ok http://192.168.1.250/:service:admin:HTTP/1.0 200 Ok
Impact This issue may be exploited by a remote attacker to e.g. gain access to sensitive information or modify system configuration.
Solution: Solution type: Mitigation Change the password as soon as possible. ...continues on next page ...

...continued from previous page ...
Vulnerability Insight As the VT 'HTTP Brute Force Logins With Default Credentials' (OID: 1.3.6.1.4.1.25623.1.0.108041) might run into a timeout the actual reporting of this vulnerability takes place in this VT instead.
Vulnerability Detection Method Reports default credentials detected by the VT 'HTTP Brute Force Logins With Default Credentials' (OID: 1.3.6.1.4.1.25623.1.0.108041). Details: HTTP Brute Force Logins With Default Credentials Reporting OID:1.3.6.1.4.1.25623.1.0.103240 Version used: 2026-06-10T06:59:19Z
References cert-bund: WID-SEC-2026-1740

[\[return to 192.168.1.250 \]](#)

2.1.2 Medium 80/tcp

Medium (CVSS: 4.8) NVT: Cleartext Transmission of Sensitive Information via HTTP
Summary The host / application transmits sensitive information (username, passwords) in cleartext via HTTP.
Quality of Detection (QoD): 80%
Vulnerability Detection Result The following URLs requires Basic Authentication (URL:realm name): http://192.168.1.250/:"WRT54GL"
Impact An attacker could use this situation to compromise or eavesdrop on the HTTP communication between the client and the server using a man-in-the-middle attack to get access to sensitive data like usernames or passwords.
Solution: Solution type: Workaround Enforce the transmission of sensitive data via an encrypted SSL/TLS connection. Additionally make sure the host / application is redirecting all users to the secured SSL/TLS connection before allowing to input sensitive data into the mentioned functions.
Affected Software/OS Hosts / applications which doesn't enforce the transmission of sensitive data via an encrypted SSL/TLS connection.
Vulnerability Detection Method Evaluate previous collected information and check if the host / application is not enforcing the transmission of sensitive data via an encrypted SSL/TLS connection. The script is currently checking the following: - HTTP Basic Authentication (Basic Auth) - HTTP Forms (e.g. Login) with input field of type 'password' Details: Cleartext Transmission of Sensitive Information via HTTP OID:1.3.6.1.4.1.25623.1.0.108440 Version used: 2023-09-07T05:05:21Z

[\[return to 192.168.1.250 \]](#)

2.1.3 Low general/icmp

Low (CVSS: 2.1)
NVT: ICMP Timestamp Reply Information Disclosure
Summary The remote host responded to an ICMP timestamp request.
Quality of Detection (QoD): 80%
Vulnerability Detection Result The following response / ICMP packet has been received: - ICMP Type: 14 - ICMP Code: 0
Impact This information could theoretically be used to exploit weak time-based random number generators in other services.
Solution: Solution type: Mitigation Various mitigations are possible: - Disable the support for ICMP timestamp on the remote host completely - Protect the remote host by a firewall, and block ICMP packets passing through the firewall in either direction (either completely or only for untrusted networks)
Vulnerability Insight The Timestamp Reply is an ICMP message which replies to a Timestamp message. It consists of the originating timestamp sent by the sender of the Timestamp as well as a receive timestamp and a transmit timestamp.
Vulnerability Detection Method Sends an ICMP Timestamp (Type 13) request and checks if a Timestamp Reply (Type 14) is received. Details: ICMP Timestamp Reply Information Disclosure OID:1.3.6.1.4.1.25623.1.0.103190 Version used: 2025-01-21T05:37:33Z
References cert-bund: CB-K15/1514 cert-bund: CB-K14/0632 dfn-cert: DFN-CERT-2014-0658

[\[return to 192.168.1.250 \]](#)