

테스트 내용(pH, EC)



설명

EC Calibration



• pH Calibration

테스트 내용(pH, EC)



1. pH Cal. 초기화면

EUSEN IS-COPCAGE)

**Sensor Calibration Program

Sensor Type: pH Sensor Value: 0.00 READ

Calibration

Tru Zero Calibration I Print Sample

PH 2 Point Buffer 4 2 Point Buffer | Demonst the pit sensor in the concal base containing pit buffer 4 apoint, starting montaining.

CL Zero Calibration I Print Sample

EC Zero Calibration I Print Sample


EC Zero Calibration I Print Sample

EC Zero Calibration I Print Sample


Com Port

Port: CORD V Read Rate: 9000 V Connect Decorrect

3. pH Cal. Step 1: 2 Point Buffer 4 Processing



4. pH Cal. Step 1 : 2 Point Buffer 4 success





7. pH Cal. Step 2 : 2 Point Buffer 7 Finish





8. pH Cal. Sensor Value Read(Verification)