

Module: Processing of industrial materials

316-332

(Processing of traditional ceramics)

Methee Promsawat

Materials Science, Division of Physical Science
Faculty of Science, Prince of Songkla University


Processing of traditional ceramics

Traditional processes:

- Casting technique
- Jiggering technique
- Throwing technique
- Mold pressing technique
- Glazing techniques




Casting technique




mixing

clay
water
sodium silicate



specific gravity



casting --> casting rate



viscometer

Casting technique




Jiggering technique



Throwing technique

Clay preparation for throwing technique

Component of body clay



Throwing technique

Clay preparation for throwing technique

Raw materials mixing



Ball milling (wet/dry)
Ball amount about 2/3 of
container




Hand mixing

Throwing technique

Clay preparation for throwing technique

Preparation of clay dough



Pug Mill



Wedging by hands

Throwing technique

Clay preparation for throwing technique



- white clay
- ball clay
- terracotta
- local clay

Throwing technique

Clay preparation for throwing technique




Throwing technique

Throwing instrument



Kick wheel



Throwing technique

Make your own a throwing wheel

DIY LED PROJECT
www.diyproject.com

มอเตอร์บัสเลส BLDC MOTER
ขนาด 20mm 500W 24V (พร้อมกล่องควบคุม)



มอเตอร์บัสเลส เกียร์ 500W 24V (พร้อมกล่องควบคุม)

★★★★★ 1 Ratings | 1 Answered Questions

Brand: No Brand | More Electrical from No Brand

฿3,790.00

Promotions

No Min Spend

Quantity

—

1

+

Only

คุณสมบัติ

แรงดันไฟ	กำลังไฟ	กระแสไฟ	ทอก	อัตราเกียร์	ความเร็วรอบ	มอเตอร์แบบ
24V	500W	20A	16N.m	6:1	400RPM	มอเตอร์แบบ Brushless



24V 20A
500W

Electric สวิตชิง เพาเวอร์ ซัพพลาย
Power Supply 24V 20A 500W

★★★★★ 2 Ratings | 2 Answered Questions

Brand: No Brand | More Electrical from No Brand

฿670.00

฿900.00 -26%



Throwing technique


Steps of throwing



Throwing technique



Free forming technique



Free forming technique



Steps after forming

- Biscuits firing at about 800 °C
- Under glaze painting
- Glazing
- Glaze firing



Steps after forming

- Over glaze painting
- Finishing
- Packing
- Shipping

