

V_{BUS}
V_{BUS}
V_{BUS}
Half-Bridge A
Half-Bridge B
Half-Bridge C
Permanent Magnet Synchronous Motor
U
V
W
V_{3V3}
V_{3V3}
V_{3V3}
$R_{SHUNT,A}$
$R_{SHUNT,B}$
$R_{SHUNT,C}$
+
-
+
-
+
-
Kelvin Connection on Layout
Current Sense Amplifier
Kelvin Connection on Layout
Current Sense Amplifier
Kelvin Connection on Layout
Current Sense Amplifier