
Rev A · robot electrical wiring

One 1S LiPo · XIAO nRF52840 Sense · Pololu 2810 LV · two PTK 7465 MG servos



Same net name = soldered connection. Blue labels identify signal wires; servo red wires never connect to XIAO 3V3 or VBUS.

USB-C is on the XIAO. Before charging: Pololu slide OFF, D2 LOW, and verify VOUT is off. Firmware interlock is not yet implemented.