

Departure Route Description

Rwy 11 - ½: Climb direct XUGPI, maintain 6000 or higher as assigned.

Communication Failure

On recognition of communication failure 10 minutes or less after take-off and in IFR weather conditions proceed as follows:

- 1. Transponder 7600;
- 2. Upon reaching XUGPI, proceed on course and climb to flight planned altitude.

Note: If communication failure occurs more than 10 minutes after take-off, comply with the appropriate procedure for communication failure enroute.

Source of Canadian Civil Aeronautical Data: © 2026 NAV CANADA All rights reserved