

Departure Route Description

- All rwy: Maintain 3000 ASL or as assigned.
- Rwy 09: Climb hdg 089° or as assigned for vectors to assigned route.
- Rwy 27: Climb hdg 269° or as assigned for vectors to assigned route.

Communication Failure

- On recognition of failure 5 minutes or less after take-off and in IFR weather conditions, proceed as follows:
- 1. Select transponder code 7600;
 - 2. Maintain 3000 for 5 minutes after take-off, then;
 - 3. Proceed directly on course and climb to flight planned altitude.
- NOTE: If communication failure occurs more than 5 minutes after take-off, comply with the appropriate procedures for Communication Failure en-route.

Source of Canadian Civil Aeronautical Data: © 2026 NAV CANADA All rights reserved