



DEPARTURE PROCEDURE

Departure Procedure

Rwy 04 – ½:

Climb between hdg 013° CCW to 221° to remain clear of CYA404.

Note: Trees to 804 ASL aprx 0.2 NM past departure end of rwy, 500' RIGHT of rwy centreline.

Rwy 13 – ½:

Climb between hdg 106° CW to 309° to remain clear of CYA404

Note: Trees to 816 ASL aprx 0.2 NM past departure end of rwy.

Rwy 18 – ½:

Climb between hdg 105° CW to 004° to remain clear of CYA404.

Rwy 22 – ½:

Climb between hdg 105° CW to 015° to remain clear of CYA404.

Note: Trees to 806 ASL aprx 0.3 NM past departure end of rwy, 400' LEFT of rwy centreline.

Rwy 31 – ½:

Climb between hdg 016° CCW to 129° to remain clear of CYA404.

No LEFT turn below 1800.

Note: Power line to 908 ASL aprx 0.9 NM past departure end of rwy.

Rwy 36 – ½:

Climb between hdg 343° CCW to 184° to remain clear of CYA404.

Note: Power line to 843 ASL aprx 0.5 NM past departure end of rwy.

DEPARTURE PROCEDURE

CYAV

Source of Canadian Civil Aeronautical Data: © 2026 NAV CANADA All rights reserved

DEPARTURE PROCEDURE
EFF 27 JAN 22

CYAV-DP

Canada Air Pilot

Effective 0901Z 14 MAY 2026 to 0901Z 9 JUL 2026