

Departure Route Description

DEPARTURE FROM Climb hdg **030°** to maintain **5000'** ASL for vectors to assigned
TKOF/LANDING AREA: route.

Communication Failure

On recognition of a communication failure 10 minutes or less after take-off, and in IFR conditions, proceed as follows:

- 1. Transponder 7600;
- 2. Upon reaching last assigned altitude proceed directly on course;
- 3. Maintain last assigned altitude for 10 minutes after take-off; then,
- 4. Climb to flight planned altitude.

NOTE: If communication failure occurs more than 10 minutes after take-off, comply with the appropriate procedure for communication failure enroute.

Source of Canadian Civil Aeronautical Data: © 2026 NAV CANADA All rights reserved