

451857N 0655324W VAR 18°W

NOT TO SCALE

CYR724
SFC TO FL250
CONT

CYR725
SFC TO 2000
CONT

RADAR or GNSS
Required.

ADVAM
210 kt

CROSI
10.4 DME
(YJH)

KAVKA
4.4 DME
(YJH)

SAINT JOHN
112.2 YJH :::: =
Ch 59

LOCALIZER 108.3
IDM ::::

DASGU
210 kt

MISSED APCH DURING COMM FAILURE
Climb to **3000** hdg **049°**. No sooner than 10 DME,
turn RIGHT direct DASGU to execute the approach
procedure again. Attempt to contact Moncton Centre
506-867-7178.

ITMAK

KEPMI

696

2900
222°
10.9 NM

2900
222°
20.3 NM

MSA YJH
2900
←090°→
←096°→

MSA YJH
2900
←096°→
←270°→

MSA YJH
2900
←096°→
←270°→

ILS RWY 05	CYSJ
EFF 20 FEB 25	