

RNAV (GNSS) X RWY 03 OPS SPEC

RESTRICTED INSTRUMENT PROCEDURE

Transport Canada Special Authorization Required.

The following conditions apply to this procedure:

- The aircraft shall be certified and equipped to fly a glide path angle of 4.8°;
- Air Crew shall be trained to fly approaches with glide path angle of 4.8° and shall be trained and familiar with conditions associated with this approach procedure;
- The PAPI system shall be operational.