

## \*\*Technical Question\*\*

Company: ELLIOTT BAY IND

Contact: Nick Miller

Part #: EllBayInd-LocOs

Rev #: noRev

Assembly WO#: 80601\_18 Date: 2019-01-09 12:59:16.456

The following item(s) need to be resolved before we can proceed with your build. Please review and advise on how to proceed. (NOTE: submitting a new BOM will reset your turn time.)

## Issue #1

Category: Parts in BOM not CPL

The following parts are in your BOM but missing from the CPL. Are they to be placed?

M150,J151,J101,J102,CON\_RX\_201,CON\_RX\_203,CON\_RX\_205,CON\_RX\_207,CON\_RX\_209,CON\_RX\_211

CON\_RX\_213,CON\_RX\_215,CON\_RX\_217,CON\_RX\_219,CON\_RX\_221,CON\_RX\_202,CON\_RX\_204,CON\_RX\_206

CON\_RX\_208,CON\_RX\_210,CON\_RX\_212,CON\_RX\_214,CON\_RX\_216,CON\_RX\_218,CON\_RX\_220,CON\_RX\_222

CON\_TX\_201,CON\_TX\_203,CON\_TX\_205,CON\_TX\_207,CON\_TX\_209,CON\_TX\_211,CON\_TX\_213,CON\_TX\_215

CON\_TX\_217,CON\_TX\_219,CON\_TX\_221,CON\_TX\_202,CON\_TX\_204,CON\_TX\_206,CON\_TX\_208,CON\_TX\_210

CON\_TX\_212,CON\_TX\_214,CON\_TX\_216,CON\_TX\_218,CON\_TX\_220,CON\_TX\_222

## Issue #2

Category: Parts in CPL not BOM

The following parts are in your CPL but missing from the BOM. Are they to be placed?

CON\_TX\_19,CON\_TX\_20,CON\_TX\_21,CON\_RX\_0,CON\_RX\_1,CON\_RX\_2,CON\_RX\_3,CON\_TX\_14,CON\_TX\_13

CON\_RX\_8,CON\_TX\_12,CON\_RX\_9,CON\_TX\_11,CON\_RX\_10,CON\_TX\_10,CON\_RX\_11,CON\_TX\_9,CON\_RX\_12

CON\_TX\_8,CON\_RX\_13,CON\_RX\_14,CON\_TX\_3,CON\_TX\_2,CON\_TX\_1,CON\_TX\_0,CON\_RX\_21,CON\_RX\_20

CON\_RX\_19,CON\_TX\_18,CON\_TX\_17,CON\_RX\_4,CON\_TX\_16,CON\_RX\_5,CON\_TX\_15,CON\_RX\_6,CON\_RX\_7

CON\_TX\_7,CON\_TX\_6,CON\_RX\_15,CON\_TX\_5,CON\_RX\_16,CON\_TX\_4,CON\_RX\_17,CON\_RX\_18,

## **Additional Comments:**

Advanced Circuits Assembly: assemblytechsupport@4pcb.com