


## Gear Box Specifications:

•	
Gear Ratio	1:77
Number of gear trains	3
Max.rated torque(kg.cm)	240
Max.permissible load in a short time(kg.cm)	720
Length L (mm)	72

## Stepper Motor Specifications:

MODEL	Phase	Step Angle	Rated Voltage	Current /Phase	Resistance /Phase	Inductance /Phase	Hol di ng Torque	Rotor Inertia
		Deg/Step	V	A	Ω	mH	kg. cm	g. cm²
57STH56-2804B	2	1.8	2. 5	2.8	0.9	2. 5	12. 6	300





## Rotation:

CW Direction	Step	A	С	В	D
	1	+		+	
	2		+	+	
	3		+		+
]	4	+			+
~	1	+		+	

CW Direction, see from the shaft end. (Only Motor)

_	_													
B		61 48				48		Production need				Zhu Guanghua	2013.	11.13
REV		Original content			Changed content			Reason of change			Name	Da	ite	
											D	ONGZHENG	МОТ	0 R
REV.	QTY	. N	0.	SIG.		DATE					56JXS300K/57STH56-2804B			
DESIC	3 N Zhu	Guanghua	2013. 11.	13 STD.			CLS. M	IA K	QTY	SCALE	PLAI	PLANET GEAR STEPPER MO		DIOK
CHECH	7						S			1:1		ODZ. 244. 00	11	REV
PROC.	_			APPR.			PAGE		0F		- UνL. Δ <sup>1</sup>		1.001	