
Linux SDK Version v0.7.0


Changes

- 1) HOP → Coin Hopper (HOP) added
- 2) Add MCD → Card Dispenser (MCD)
- 3) Changed the timeout time of Moving/Fixing and ClearAllData commands from 3 seconds to 6 seconds in EPP PCI5.0 (Time delay occurs when EPP logs are accumulated)
- 4) Resolves an error in which Track3 data is normal but length is set to 0 during MCR M/S Read
- 5) Add HOP, MCD devices to LxDeviceDiagnostic and include in SDK. Updated to Version V1.0.0.1 (Same UI as Windows Diagnostics)
- 6) Changed from LxKeyManagement terminal mode to GUI (same UI as Windows KeyManagement)
- 7) LxFWDownloader was developed to change from terminal mode to GUI (same UI as Windows firmware download)
- 8) Test program (TP) GUI mode development (LxDevTP), existing terminal mode (HmDevTP)

[LxDeviceDiagnostic GUI]



[LxKeyManagement GUI]



[LxFWDownloader GUI]



(cont)

[LxDevTP GUI]

