	Month	September			October				November				December				January				
	Week start	5 12	19 26	3	10	17 2	1 31	7	14	21	28	5	12	19	26	2	9	16	23	30	
	Project week	16 17	18 19	20	21	22 2	3 24	25	26	27	28	29	30	31	1	2	3	4	5	6	
	Integration:																				
<b>1</b> a	Teleoperation with QP			L																	
1b	Reference processing			L																	
1c	Impact/contact monitoring																				
1d	RS QP control																				
	Research:																				
2a	Passive impact absorption			ı																	
2b	Contact monitoring			ı																	
	Miscelaneous:																				
	Final data collection			L																	
	Finish report draft			L																	
	Report finalizing			L						•											
	Prepare presentation			L																	
	Buffer			L																	
															Bre	eak			81	Мo	
																			sin	ce	