		Month						November				December				January				
		Week start				24				21 28					26	2	9	16	23	30
		Project week	20	21	22	23	24	25	26	27 28	29	3	0	31	1	2	3	4	5	6
		Integration:																		
1a	95%	Teleoperation with QP																		
1b	95%	Reference processing																		
1c	100%	Impact/contact monitoring																		
1d	60%	RS QP control																		
		Research:																		
2a	100%	Passive impact absorption																		
2b	100%	Contact monitoring																		
		Miscelaneous:																		
		Final data collection																		
		Finish report draft																_		
		Report finalizing											ı							
		Prepare presentation							_											
		Buffer																		
															Bre	eak			8	Mo
																			sir	ice