		Month					November				December				January					
		Week start																	23	30
		Project week	20	21	22	23	24	25	26	2	7 28	29	30	31	1	2	3	4	5	6
		Integration:			_															
1a	99%	Teleoperation with QP																		
1b	100%	Reference processing		_						i										
1c	100%	Impact/contact monitoring																		
1d	90%	RS QP control																		
		Research:																		
2a	100%	Passive impact absorption				_				ļ.,										
2b	100%	Contact monitoring																		
		Miscelaneous:																		
	30%	Final data collection																		
	15%	Finish report draft																		
		Report finalizing after feedback																		
		Prepare presentation				_						_								
		Buffer																		
															Bre	eak			81	Moi
																			sin	ice :