	Month					October					November				December				January					
	Week start												21								9	16	23	30
	Project week	16	17	18	19	20	21	22	23	24	25	26	27	28	29	3	0 3	1	1	2	3	4	5	6
	Integration:																							
1a	Teleoperation with QP																							
1b	Reference processing				_																			
1c	Impact/contact monitoring																							
1d	RS QP control																							
	Research:																							
2a	Passive impact absorption																							
2b	Contact monitoring																							
	Miscelaneous:																							
	Final data collection																							
	Finish report draft																							
	Report finalizing																							
	Prepare presentation											_												
	Buffer																							
																		I	Bre	ak			8	Мо
																							si	nce