		Month	October					N	ove	mb	er	December				January				
		Week start	3	10	17	24	31	7	14	21	28	5	12	19	26	2	9	16	23	30
		Project week	20	21	22	23	24	25	26	27	28	29	30	31	1	2	3	4	5	6
		Integration:																		
1a	95%	Teleoperation with QP																		
1b	95%	Reference processing																		
1c	100%	Impact/contact monitoring																		
1d	60%	RS QP control																		
		Research:																		
2a	100%	Passive impact absorption																		
2b	100%	Contact monitoring																		
		Miscelaneous:																		
		Final data collection												_						
		Finish report draft																		
		Report finalizing																		
		Prepare presentation																		
		Buffer																		
															Bre	eak			8	Mor
																			sir	ice s