The bypass caps Cl..C4 are placed on the bottom side of the PCB

MIDIbox Hardware Platform MBHP_DINX4_V2a (C) T. Klose 2002-06-23