

The bypass caps Cl..C5 are placed on the bottom side of the PCB

MIDIbox Hardware Platform

MBHP\_DOUTX4\_V2a

(C) T. Klose 2002-06-23