
249.

L cost V cost.

LW317

$$\frac{1}{10} = \frac{4 \times 4}{10} = 0, h A$$

tch = 2,3v x 2 = 4,6 v



R1 = 1K R2 = 2,7 K ~ Vo = 4,625 V



TO 220