

Safety Manual — Rotating Equipment Operations

1. General Safety Requirements

All personnel working on or near rotating equipment (pumps, compressors) must comply with plant Permit to Work (PTW) procedures and wear appropriate PPE, including hearing protection in compressor areas.

2. Lockout / Tagout (LOTO)

Before any maintenance activity on equipment such as P-102 or the C-200 series compressors, the equipment must be isolated electrically and mechanically, and a Lockout/Tagout procedure must be applied and verified by two authorized personnel.

3. High Temperature Hazards

Overheated equipment presents burn hazards. If a pump or compressor casing or bearing housing is suspected to exceed 60 degrees Celsius, personnel must not touch the surface directly and should use a non-contact infrared thermometer to verify temperature before approaching for inspection.

4. Emergency Shutdown Criteria

Equipment must be shut down immediately (do not wait for maintenance dispatch) if any of the following occur:

- Bearing temperature exceeds the trip setpoint defined in the equipment manual.
- Visible smoke, unusual smell, or sparking from the motor or bearing housing.
- Sudden, severe increase in vibration.
- Leakage of process fluid at the mechanical seal beyond the allowed drip rate.

5. Reporting

All abnormal conditions, including recurring high-temperature alarms on equipment such as P-102, must be logged in the plant incident/near-miss system, even if the equipment was not shut down, to support trend analysis and preventive action.