

These five holes are connected inside the breadboard so you can use them to hook parts together