


## Wire your light sensor to the Trinket like so ...



The resistor for the light sensor is brown-black-orange-gold (10kohm)