

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	7.000.21							
1	lw 291st	24952.54				NW K	cenc	on
No	orth-South Road Name	Project No. Shee	et No. Ir	ntersection N	o.	East-W	est Ro	oad Name)
		Calibration Date (mm/dd/yy)					k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
•	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a	Length 1	13.6	ĺ				Position 3 Positions
•	k (MB), GFS must be \leq Slope of the Road, at	Cross Slope 1	13.6	≤ 2.0%		>2.0%		3
•	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)	Υ	Υ		N		3A
5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.		Lip Height		1/4"		>1/4"		2 North
length Y must be minimum 5.0 ft.		Gutter Flow Slope	A 1.9	≤ *		>*		
		Curb Running Slope (avg)	5.22	≤ 8.3%		>8.3%		1 Ramp Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	2.8	≤ 5.0%		> 5.0%		Position
	o <u>Standard Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (require private developme
1		Detectable warning extends full width of ramp throat opening	Υ	Y		N		
Run I		TURN SPACE LANDING	G NON	IE	Pass		Fail	
		Width X	3.7	≥ 4.0'		< 4.0'		
		Length Y	5	≥ 4.0'*¹		< 4.0'*1		Comments:
Country	Side -	Back of Ramp Obstruction (Y/N)	N	≥ 5.0' * 1		< 5.0'*1		RR1 ICRR
PI	SERVICE AND TO SERVICE	Slope X		≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		
	Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
←	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mn
\mathcal{I}	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
₹Ţ	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	3.7	≥ 4.0'		< 4.0'		Darrell Wyant 5263 Print name clearly Certificat
•	Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of	Road	1.5		3J Consulting
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





