

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

- Contract			-		_	_		
Nw 287 ave	24952.54				Nw S	hadd	lon st	
North-South Road Name	Project No. Shee	et No.	Intersection N	0.	East-W	est Ro	oad Name	
	Calibration Date	8/13/2024	(mm/dd/	/yy)			k - ') ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	
Ramp Style PR	RAMP RUN 1		≤ 8.3%	Pass	>8.3%	Fail	Corner	R
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a	Running Slope 1 Length 1 Cross Slope 1	10.1	≤ 2.0%		>2.0%		Corner Positions 3	7
Nidblock (MB), GFS must be \leq Slope of the Road, at gnalized or Uncontrolled (SU), GFS must be \leq	Detectable Warning (Y,N)		Y		N		3A -	3
0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%. If Back of Ramp Obstruction is Yes, turn space	Lip Height		1/4"		>1/4"		2 North	2
ngth Y must be minimum 5.0 ft.	Gutter Flow Slope N/ Curb Running Slope (avg)	/A 2.8	≤ * ≤ 8.3%		>* >8.3%		4 Ramp 1	
Clear Space area is the width of Ramp Run 1 and ktends 4.0 ft into the roadway.	Counter Slope (+/-) *2	3.9	≤ 8.3%		> 5.0%		Ramp Position	
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	0.8	< 5.0'		≥ 5.0'		PE Stamp (r. private deve	•
	Detectable warning extends full width of ramp throat opening		Y		N			
/* * * / * // * * /	TURN SPACE LANDIN	G NC	ONE	Pass		Fail		
Pun 1	Width X	4.0	≥ 4.0'		< 4.0'			
Counter slope Guster Flow slope	Length Y	6.5	≥ 4.0'*1		< 4.0'*1		Comments:	
	Back of Ramp Obstruction (Y/N)		≥ 5.0'*1		< 5.0'*1			
PERPENDICULAR RAMP (PR)	Slope X	0.7	≤2.0%		>2.0%			
Pedestrian Access Route (to measure Clear Width)	Slope Y	1.6	≤2.0%		>2.0%			
Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	able		Pass		Fail] r	
Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature	Date
A Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Darrell Wyant	5263
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'			ertifi
Gutter Flow Slope (as directed)	Intersection Control Type		Slope of	Road	0.3		3J Consulting	
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





