	WASHINGTON COUNTY
	OREGON

## **ADA Curb Ramp New Construction Inspection Form (Parallel)**

OREGON		_			
NW 309th St	24952.54 NW North Ave				
North-South Road Name	Project No. Sheet No.	Intersection No.	East-West R	1 //	n.gov/odot/Engineering/Documents
	Calibration Date	10/22/2024 (mm/dd/yy)			_ExhibitA.pdf for more corner styles. County corner numbering system.
- R	AMP RUN 1	Pass	Fail		15.4
PL		1.9 ≤ 2.0% ■ >		2	Corner
Ramp Style R	unning Slope 1			Corner	Positions 1
*The passing value for Gutter Flow Slope (GFS)	ross Slope 1	≤ 2.0%   ■ >	2.0%	Position 3	5 2A
	etectable Warning	Y Y	N		
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	ip Height	0 ≤ 1/4" <b>■</b> >	1/4"	3A	<b>↑</b>
	Gutter Flow Slope	1.5 ≤ *	>*	2	North
	Curb Running Slope(avg)	1.82 ≤ 8.3% ■ >	8.3%>	4	Pare 1
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	2.7 ≤ 5.0%  ■ >	5.0%	2	Ramp 1
*2 Clear Space area is the width of Ramp Run 1	et. warning full width of ramp	Y	N	Ramp Position	5
and extends 4.0 ft into the roadway.	AMP RUN 2	Pass	Fail		PE Stamp (required for
R	unning Slope 2	5.9 ≤ 8.3% ■ >	8.3%		private development)
See also <u>Standard Drawings</u> to assess provisions not shown:	ength 2	6			
(inlets, alignment, etc.)	ross Slope 2	≥ 2.0%  >	2.0%		
R	AMP RUN 3	Pass	Fail		
R	tunning Slope 3	4.2 ≤ 8.3% ■ >	8.3%		
15 Fun 3 735 77	ength 3	7.5			
Accommodated the country of the coun	Cross Slope 3	12.00/	2 0%		
Counter slope Guiter Flow slope	<u> </u>			Comments:	_
TI TI	URN SPACE	Pass	Fail	Asphalt not completed.	
V	Vidth X	5.1 ≥ 4.0'	< 4.0'	, toprian not completed	•
PARALLEL RAMP (PL)	ength Y	5.45 ≥ 4.0'*1 <b>■</b> <	4.0'*1		
PARALLEL RAMP (PL)	ack of Ramp Obstruction (Y/N)	N ≥ 5.0'*1 <	5.0'*1		
Pedestrian Access Route (to measure Clear Width)	lope X (Cross Slope 1)	1.4 ≤ 2.0% ■ >	2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	lope Y (Running Slope 1)	1.9 ≤ 2.0% ■ >	2.0%		
STEAM STANDARD CONTRACTOR STANDARD CONTRACTOR CONTRACTO	/IISCELLANEOUS	Pass	Fail	Inspector's Signature	Date (mm/dd/yy
Counter Slope (5.0% max.)	lear Width (feet)	≥ 4.0' <	< 4.0'	Darrell Wyant	52638
* If constrained at back of walk, min, Y length is 5'.			, <del>, , , ,</del> _	Print name clearly	Certification No
Gutter Flow Slope (as directed)	ntersection Control Type	SU Slope of Rd.		3J Consulting	
Н	lorizontal Gaps	○ ≤ 1/2"   ■ >	• 1/2"	Company/Agency	



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





