

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

N. CO.	0.4050.54	—— r			1		
Nw 289 ave	24952.54		Intercenting N	•	Nw ca		
North-South Road Name			Intersection N		East-W	est Ro	pad Name
	Calibration Date 8	3/6/2024	(mm/dd/	/yy) 			к -) - y ‡ #
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	Corner
The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a	Length 1	13.1					Position 3 Positions 2A
Midblock (MB), GFS must be \leq Slope of the Road, at	Cross Slope 1		≤ 2.0%		>2.0%		
Signalized or Uncontrolled (SU), GFS must be \leq 5.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.	Detectable Warning (Y,N)		Y		N		3A North
	Lip Height		1/4"		>1/4"	Ш	2 North
¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Gutter Flow Slope	A 3.7	≤ *		>*		4 Ramp 1
_	Curb Running Slope (avg)	2.32	≤ 8.3%		>8.3%		Ramp Positions
² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Counter Slope (+/-) *2	5.2	≤ 5.0%		> 5.0%		Position
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)	2.0	< 5.0'		≥ 5.0'		PE Stamp (required private developmen
The state of the s	Detectable warning extends full width of ramp throat opening		Y		N		
/ w w w / 5 / w w	TURN SPACE LANDING	G NO	NE 🔳	Pass		Fail	
Pun 1	Width X	5.4	≥ 4.0'		< 4.0'		
Counter slope Guryer Flow slope	Length Y	5.75	≥ 4.0'*1		< 4.0'*1		Comments:
	Back of Ramp Obstruction (Y/N)		≥ 5.0'*1		< 5.0'*1		KKIICKK
PERPENDICULAR RAMP (PR)	Slope X	2.8	≤2.0%		>2.0%		
Pedestrian Access Route (to measure Clear Width)	Slope Y		≤2.0%		>2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ble		Pass		Fail	
Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (mm/c
Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)		≥ 4.0'		< 4.0'		Darrell Wyant 52638 Print name clearly Certification
Gutter Flow Slope (as directed)	Intersection Control Type		Slope of	Road	2.3		3J Consulting
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





