WASHINGTON COUNTY						
OREGON						
NW 309th St						
North-South Road Name						

ADA Curb Ramp New Construction Inspection Form (Parallel)

	NW 309th St	24952	54					NW I	North Ave			
	North-South Road Name	Project	No.	Shee	et No.	Intersection No		East-W	/est Road Nar	, ,,	oregon.gov/odot/Engine	
			Calibration Date 10/22/2024 (mm/dd/yy)							/ADA_ExhibitA.pdf for mgton County corner num		
	PL	RAMP RUN 1					Pass	ſ	ail 2			2
	Ramp Style	Running Slope 1 Cross Slope 1 Detectable Warning			1.9	1.9 ≤ 2.0% ■ >			Corne		Corner Positions	1
*The	passing value for Gutter Flow Slope (GFS)				1.4	≤ 2.0%	>	2.0%	Positi	ion 3	5	2A
depe	nds on the Intersection Control Type. At a				Y	Υ	Υ 🔳			1	2	3
	lock (MB), GFS must be ≤ Slope of the , at Signalized or Uncontrolled (SU), GFS	Lip Height Gutter Flow Slope			0	≤ 1/4	≤ 1/4" ■ >			3A 1	1	Ÿ
must	be ≤ 5.0%, and at Stop				1.5	≤ *	>*		2	North	2	
or Yield (SY), GFS must be ≤ 2.0%.		Curb Running Slope(avg)								(F	
1 If	Back of Ramp Obstruction is Yes, turn e length Y must be minimum 5.0 ft.	Counter Slo	pe (+/-)	2	2.7	≤ 5.0%	>	5.0%	2	4	Ramp 1	
•	ear Space area is the width of Ramp Run 1	Det. warnin	full widt	h of	ramp Y	Υ		N [Ramp Positi		5	
and e	extends 4.0 ft into the roadway.	RAMP RUN 2				Pass Fail				PE Stamp (required for	
		Running Slo	e 2		5.9	≤ 8.3%	6 ■ >	8.3%	$\neg \parallel$			velopment)
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)		Length 2			6				_			
		Cross Slope	2		2	≤ 2.0%	۶ ا	2.0%				
Counter slope PARALLEL RAMP (PL)		RAMP RUN	3				Pass	ſ	-ail			
		Running Slo	e 3		4.2	≤ 8.3%	6 ■ >	8.3%				
		Length 3			7.5							
		Cross Slope 3										
		TURN SPACE				Pass Fai			Fail ┌───			
		Width X			5.	≥ 4.0'		< 4.0'	Aspr	Asphalt not completed.		
		Length Y			5.	≥ 4.0'*	:1 🔳 <	4.0'*1				
	PARALLEL RAMP (PL)	Back of Ramp	Obstructio	n (Y/N	1) N	≥ 5.0'*	:1 🔳 <	5.0'*1				
	Pedestrian Access Route (to measure Clear Width)	Slope X (Cros	s Slope 1)		1.2	≤ 2.0%	>	2.0%				
	Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Run	ing Slope 1)	1.9	≤ 2.0%	, ■ >	2.0%				
	← Running Slope (8.3% max.)	MISCELLANEOUS				Pass Fa			ail Inspect	Inspector's Signature		
	Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width	(feet)			≥ 4.0'		< 4.0'	Darr	ell Wyant		52638
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Intersection Control Type			s			`		Print name clearly		
	Gutter Flow Slope (as directed)	• •		0	≤ 1/2'		> 1/2"	3J Coi	nsulting			
		Horizontal Gaps				3 1/2		1/2	Compa	iny/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





