

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

Nw Kaye	24952.54				Nw Si	haddo	on
North-South Road Name	Project No. She	eet No. Int	ersection N	0.	East-W	est Ro	ad Name
	Calibration Date	7/30/2024	(mm/dd/	' yy)			k -) · · · · · · · · · · · · · · · ·
Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail	1 Corner Corner
	Length 1 Cross Slope 1 Detectable Warning (Y,N)	11.3	≤ 2.0% Y		>2.0% N		Position 3 Positions 2 2A 3
	C. Marie Elassi Classic	0	1/4" ≤ *		>1/4" >*		North
length Y must be minimum 5.0 ft. ² Clear Space area is the width of Ramp Run 1 and extends 4.0 ft into the roadway.	Curb Running Slope (avg) Counter Slope (+/-) *2	1.56	≤ 8.3% ≤ 5.0%		>8.3% > 5.0%		Ramp Position
See also <u>Standard Drawings</u> to assess provisions not shown: (inlets, alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (require private developm
Counter slope	Detectable warning extends full width of ramp throat opening		Υ		N		
	TURN SPACE LANDIN	NG NONE	≥ 4.0'	Pass	< 4.0'	Fail	
	Length Y		≥ 4.0'*1		< 4.0'*1		Comments: RR1 ICRR
	Back of Ramp Obstruction (Y/N) <u>Y</u>	≥ 5.0' * ¹		< 5.0'*1		THE TOTAL
PERPENDICULAR RAMP (PR) Pedestrian Access Route (to measure Clear Width)	Slope X		≤2.0%		>2.0%		
Detectable Warning Surface	Slope Y MISCELLANEOUS Travers	sable	≤2.0%	Pass	>2.0%	Fail	
Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature Date (m
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Flare Slope 2 Clear Width (feet)	5.2	≤ 10% ≥ 4.0'		<10% < 4.0'		Darrell Wyant 526 Print name clearly Certifica
Gutter Flow Slope (as directed)	Intersection Control Type	SY	Slope of				3J Consulting
	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





