	WASHINGTON COUNTY	ļ				
6	OREGON					
	NW West Union					
	North-South Road Name					
		PL				
		Ramp Sty				
*The passing value for Gutter Flow Slope (GFS) depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%, and at Stop or Yield (SY), GFS must be ≤ 2.0%.						
* ¹ l [.] spa	st1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.					
* ² (and	Clear Space area is the width of R extends 4.0 ft into the roadway.	amp Run 1				

(inlets, alignment, etc.)

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

ADA Curb Ramp New Construction Inspection Form (Parallel)

23885.56

Ramp Style

-	Duningt No.				
	Project No. Sheet No.	Intersection No.	East-West F	t Road Name See https://www.oregon.gov/odot/Engineering/Docum _RoadwayEng/ADA_ExhibitA.pdf for more corner st	
	Calibration Date	(mm/dd/yy)		Use Washington County corner numbering system	n.
	RAMP RUN 1	Pass	Fail	-	2
	Running Slope 1	≤ 2.0%	2.0%	Corner Positions	3
	Cross Slope 1	≤ 2.0% >	2.0%	Position 3	*
	Detectable Warning	Y ■	N)
	Lip Height	≤ 1/4" ■ >	1/4"	3A 1	
	Gutter Flow Slope	0.4 ≤ *	> *	North	
	Curb Running Slope(avg)	3.96 ≤ 8.3% ■ >	8.3%>		_
	Counter Slope (+/-)*2	5.9 ≤ 5.0% ■ >	5.0%	Ramp 1	
	Det. warning full width of ramp	У	N	Ramp 5	
	RAMP RUN 2	Pass	Fail		or
	Running Slope 2	9.6 ≤ 8.3% >	8.3%	private development	
	Length 2	10.1			
	Cross Slope 2	≤ 2.0% >	2.0%		
RAMP RUN 3		Pass	Fail		
	Running Slope 3	5.1 ≤ 8.3% ■ >	8.3%		
	Length 3	7.1			
	Cross Slope 3	≥ 2.0% >	2.0%		
	TURN SPACE	Pass	Fail	Comments:	
	Width X	5.0 ≥ 4.0'	< 4.0'	DWS IITD Fails turn space	
	Length Y	5.0 ≥ 4.0'*1 ■ <	4.0'*1		
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1 ■ <	5.0'*1		
	Slope X (Cross Slope 1)	≤ 2.0% >	2.0%]	
	Slope Y (Running Slope 1)	≤ 2.0% >	2.0%		
	MISCELLANEOUS	Pass	Fail	I Inspector's Signature Date (mm	n/dd/y
	Clear Width (feet)	5.0 ≥ 4.0' <	< 4.0'	Darrell Wyant 5263	88
	Intersection Control Type	Slope of Rd.	0.2	Print name clearly Certificat	ion N
Horizontal Gaps			1/2"	3J Consulting	
		_ = 1,2		Company/Agency	

NW Stewart LN



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





