

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	1.000000								
N	lw 289th	24952.54				Nw Ka	aye		
No	orth-South Road Name	Project No. Shee	et No. In	tersection N	lo.	East-W	est Ro	pad Name	-)
		Calibration Date	7/30/202	(mm/dd,	/yy)			k) y ‡ #	· · · · · · · · ·
	Ramp Style PR	RAMP RUN 1 Running Slope 1		≤ 8.3%	Pass	>8.3%	Fail		Corner
	ssing value for Gutter Flow Slope (GFS)	Length 1					Position 3	ositions 2A	
•	s on the Intersection Control Type. At a k (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1	11.2	≤ 2.0%		>2.0%		1	3
•	ed or Uncontrolled (SU), GFS must be ≤ and at Stop or Yield (SY), GFS must be ≤ 2.0%.	Detectable Warning (Y,N) Lip Height	Y	Υ		N . 1 / 4 !!	Н	3A 3	North
¹ If Back	of Ramp Obstruction is Yes, turn space	Gutter Flow Slope	0	1/4" ≤ *		>1/4" >*			1
_	must be minimum 5.0 ft. Space area is the width of Ramp Run 1 and	Curb Running Slope (avg)	0.8	≤ 8.3%		>8.3%		1 Ramp 4 P	Ramp 1
	4.0 ft into the roadway.	Counter Slope (+/-) *2	5.2	≤ 5.0%		> 5.0%		Position	PE Stamp (require
	o Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'			private developm
/.	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Υ		N			
Run I Sun Stope Counter stope		TURN SPACE LANDING	G NON	E	Pass		Fail		
		Width X	2.2	≥ 4.0'		< 4.0'			
		Length Y		≥ 4.0'*1		< 4.0'*1		Comments:	
		Back of Ramp Obstruction (Y/N)	Y	≥ 5.0'*¹		< 5.0'*1		,	
P	ERPENDICULAR RAMP (PR) Pedestrian Access Route (to measure Clear Width)	Slope X		≤2.0%		>2.0%			
	Detectable Warning Surface	Slope Y		≤2.0%		>2.0%			
	Cross Slope (2.0% max.)	MISCELLANEOUS Traversa	ıble		Pass		Fail		
←	Running Slope (8.3% max.)	Flare Slope 1		≤ 10%		< 10%		Inspector's Signature	Date (m
1	Counter Slope (5.0% max.)	Flare Slope 2		≤ 10%		<10%		Downell Whent	
	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	4.5	≥ 4.0'		< 4.0'		Darrell Wyant Print name clearly	526 Certifica
-	Gutter Flow Slope (as directed)	Intersection Control Type	ξŸ	Slope of	Road	1.7		3J Consulting	
		Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





