

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

| 100 | and contract | | | | | | | | | | |
|-----------------------------|----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|--------|----------------|------|-------------|---------|----------------------------------|------------------------|---------------|--|
| N | W Kaye | 24952.54 | | | | | NW King | | | | |
| Noi | rth-South Road Name | Project No. Shee | et No. | Intersection N | lo. | East-W | est Ro | oad Name | |) | |
| | | Calibration Date | | (mm/dd, | /yy) | | | k - `) y ‡ # | | | |
| | Ramp Style PR | RAMP RUN 1 Running Slope 1 | | ≤ 8.3% | Pass | >8.3% | Fail | 1 4 | Corner | 8 | |
| • | ssing value for Gutter Flow Slope (GFS) | Length 1 | | i | | | | Position 3 | Positions | 2A 1 | |
| • | on the Intersection Control Type. At a (MB) , GFS must be \leq Slope of the Road, at | Cross Slope 1 | 10.5 | ≤ 2.0% | | >2.0% | | | | 3 | |
| _ | d or Uncontrolled (SU), GFS must be ≤ d at Stop or Yield (SY), GFS must be ≤ 2.0%. | Detectable Warning (Y,N) | Υ | Υ | | N | | 3A | North | | |
| | of Ramp Obstruction is Yes, turn space | Lip Height Gutter Flow Slope | 0 | 1/4" ≤ * | | >1/4" >* | | 1 | 4 | 2 | |
| | | Curb Running Slope (avg) | 9.44 | ≤ 8.3% | | >8.3% | | 4 | Ramp 1 | | |
| | pace area is the width of Ramp Run 1 and 4.0 ft into the roadway. | Counter Slope (+/-) *2 | 6.4 | ≤ 5.0% | | > 5.0% | | Ramp Position | 5 | | |
| | Standard Drawings to assess provisions not shown: lignment, etc.) | Longest distance from corner to back of curb (see dwg on BT form) | | < 5.0' | | ≥ 5.0' | | | PE Stamp private de | | |
| /. | X X X X X X X X X X X X X X X X X X X | Detectable warning extends full width of ramp throat opening | | Y | | N | | | | | |
| / w w / 4 / 1 / 1 / 1 | | TURN SPACE LANDIN | G NOI | NE | Pass | | Fail | | | | |
| | Run 1 / ** *** | Width X | 2.3 | ≥ 4.0' | | < 4.0' | | | | | |
| Counter slope Counter slope | | Length Y | | ≥ 4.0'*1 | | < 4.0'*1 | | Comments: | <u> </u> | | |
| | | Back of Ramp Obstruction (Y/N) | Y | ≥ 5.0'*¹ | | < 5.0'*1 | | RR1 ICRR | | | |
| P | ERPENDICULAR RAMP (PR) | Slope X | | ≤2.0% | | >2.0% | | | | | |
| •••••• | Pedestrian Access Route (to measure Clear Width) Detectable Warning Surface | Slope Y | | ≤2.0% | | >2.0% | | | | | |
| ********* | Cross Slope (2.0% max.) | MISCELLANEOUS Traversa | able | | Pass | | Fail | | | | |
| | Running Slope (8.3% max.) | Flare Slope 1 | | ≤ 10% | | < 10% | | Inspector's Signature | | Date | |
| | Counter Slope (5.0% max.) | Flare Slope 2 | | ≤ 10% | | <10% | | Dorroll Wyont | | | |
| T | Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'. | Clear Width (feet) | 4.35 | ≥ 4.0' | | < 4.0' | | Darrell Wyant Print name clearly | | 52 Certifi | |
| - | Gutter Flow Slope (as directed) | Intersection Control Type | SY | Slope of | Road | 3.0 | | 3J Consulting | | | |
| | | Horizontal Gaps | | ≤1/2" | | > 1/2" | | Company/Agency | | - | |



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





