WASHINGTON COUNTY
OREGON
NW 309th St
AL ILC ILD IAI

ADA Curb Ramp New Construction Inspection Form (Parallel)

NW 309th St	24952.54	NW North Ave				
North-South Road Name	Project No. Sheet No.	Intersection No.	East-\	West Road Nam		
	Calibration Date 1	0/22/2024 (mm	ı/dd/yy)		_RoadwayEng/ADA_ExhibitA.pdf for m Use Washington County corner numl	
PL R	RAMP RUN 1		Pass	Fail 2		2
_R	Running Slope 1	1.2 ≤ 2.0%	= > 2.0%	Corne	Corner	
Kamp Style	Cross Slope 1	1.4 ≤ 2.0%	= > 2.0%	Position	3 🖂	2A 1
The passing value for dutter Flow Slope (GFS)	•				5 2	0_0
depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the	Detectable Warning	Y	■ N			3
Road, at Signalized or Uncontrolled (SU), GFS	ip Height	0 ≤ 1/4"	1/4 "		3A	
	Gutter Flow Slope	0.6 ≤ *	>*		North	
or Yield (SY), GFS must be ≤ 2.0%.			- 0 20/s			Á
*1 If Back of Ramp Obstruction is Yes, turn	Curb Running Slope(avg)	0.6 ≤ 8.3%		<u> </u>	Ramp 1	
space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	≤ 5.0%	 > 5.0%		Positions Positions	
* ² Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	Υ	N	Ramp Position	2.1	
	RAMP RUN 2		Pass	Fail	PE Stamp (required for
F	Running Slope 2	6.9 ≤ 8.3%	> 8.3%		private dev	relopment)
See also Standard Drawings to assess provisions not shown:	ength 2	7.5				
(inlets, alignment, etc.)	Cross Slope 2	2 ≤ 2.0%	> 2.0%			
R	RAMP RUN 3		Pass	Fail		
y F	Running Slope 3	5.4 ≤ 8.3%	> 8.3%			
18 Run 3 18 Run 1 Run 2	ength 3	6				
Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	Cross Slope 3	1.9 ≤ 2.0%	= > 2.0%			
Counter slope Gutter Tiow slope	URN SPACE			Fail	ients:	
	Width X	5.0 ≥ 4.0'	4.0 < 4.0	5 in c	core hole in RR2. Asphalt no	ot
	ength Y	5.55 ≥ 4.0'*1	< 4.0'*1	comp	oleted.	
() a describe (d arrive () b)	-					
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1	< 5.0'*1			
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.4 ≤ 2.0%	2.0%			
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	1.2 ≤ 2.0%	= > 2.0%			
Running Slope (8.3% max.)	MISCELLANEOUS		Pass	Fail Inspecto	or's Signature	Date (mm/dd/yy
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	≥ 4.0'	< 4.0'	Darre	ell Wyant	52638
* If constrained at back of walk, min. Y length is 5'.	ntersection Control Type	SU Slope o			,	Certification N
Gutter Flow Slope (as directed)		o ≤ 1/2"	> 1/2"	3J Con	nsulting	
-	lorizontal Gaps	2 1/2		Compar	ny/Agency	



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





