	WASHINGTON COUNT
	OREGO

ADA Curb Ramp New Construction Inspection Form (Parallel)

NW Curtis	23885.56 NW Pacific						
North-South Road Name	Project No. Sheet No.	Intersection No.	East-V	West Road Na		egon.gov/odot/Engine	
	Calibration Date	7/10/2024 (mm	/dd/yy)			DA_ExhibitA.pdf for mon County corner num	
PL	RAMP RUN 1	ŗ	Pass	Fail			2
	Running Slope 1	1.7 ≤ 2.0%	= > 2.0%	Corn	er	Corner	~ W
Ramp Style	Cross Slope 1	1.7 ≤ 2.0%	= > 2.0%	Posit	ion 3	Positions	2A 1
*The passing value for Gutter Flow Slope (GFS)	·					5 2	
depends on the Intersection Control Type. At a Midblock (MB), GFS must be ≤ Slope of the	Detectable Warning	N Y	N				3
Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	≤ 1/4"	> 1/4"		3A	\wedge	
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	0.7 ≤ *	■ >*		2	North	0
or Yield (SY), GFS must be ≤ 2.0%.	· –			H	1	,	Á
* ¹ If Back of Ramp Obstruction is Yes, turn	Curb Running Slope(avg)	7.18 ≤ 8.3%	> 8.3%>	<u> </u>	4	Ramp 1	
space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	^{5.5} ≤ 5.0%	> 5.0%		2	Positions	
* ² Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	YY	■ N	Ram Posit		5	
and extends 4.0 ft into the roadway.	RAMP RUN 2		Pass	Fail		PE Stamp (required for
	Running Slope 2	5 ≤ 8.3%	> 8.3%			private dev	velopment)
See also Standard Drawings to assess provisions not shown:	Length 2	7.6					
(inlets, alignment, etc.)	Cross Slope 2	2.3 ≤ 2.0%	> 2.0%				
	RAMP RUN 3		Pass	Fail			
	Running Slope 3	5.6 ≤ 8.3%	> 8.3%				
18 Page 3 The State of the 2	Length 3	7.7					
1 Pun 2 1 1	Cross Slope 3	1.6 ≤ 2.0%	a > 2.0%				
Counter slope Gutter Now slope	TURN SPACE			Fail	ments:		
SIL THE	Width X	5.0 ≥ 4.0'	< 4.0'		olock east side		
		> 4 01*1		HI			
PARALLEL RAMP (PL)	Length Y			닏Ⅱ			
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	≥ 5.0'*1	< 5.0'*1	$\Box \parallel$			
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.7 ≤ 2.0%	2.0%				
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	1.7 ≤ 2.0%	2 .0%				06/05/24
Running Stope (8.3% max.)	MISCELLANEOUS		Pass	Fail Inspec	tor's Signature		Date (mm/dd/y
Counter Slope (5.0% max.)	Clear Width (feet)	5.0 ≥ 4.0'	< 4.0'	Dar	rell Wyant		52638
Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Intersection Control Type	SU Slope o			ame clearly		Certification N
Gutter Flow Slope (as directed)		≤ 1/2"	> 1/2"	3J Cc	onsulting		
	Horizontal Gaps	<u> </u>		Compa	any/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





