	WASHINGTON COUNTY			
	OREGON			
	NW Curtis St			
	North-South Road Name			

ADA Curb Ramp New Construction Inspection Form (Parallel)

NVV Curtis St	23885.56	NV	V Highland Ct	
North-South Road Name	Project No. Sheet N	No. Intersection No. East	-West Road Name	See https://www.oregon.gov/odot/Engineering/Documents RoadwayEng/ADA ExhibitA.pdf for more corner styles.
	Calibration Dat	7/2/2024 (mm/dd/yy)		Use Washington County corner numbering system.
PL	RAMP RUN 1	Pass	Fail 2	2
Ramp Style	Running Slope 1	1.4 ≤ 2.0% ■ > 2.0%	Corner	Corner
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	3.6 ≤ 2.0% > 2.0%	Position	3 5 24
depends on the Intersection Control Type. At a	Detectable Warning	N Y N		
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	 Lip Height	0 ≤ 1/4" ■ > 1/4"		3A -
must be \leq 5.0%, and at Stop	Gutter Flow Slope	1.5 < * II > *		North
or Yield (SY), GFS must be ≤ 2.0%.	·		H	2
* ¹ If Back of Ramp Obstruction is Yes, turn	Curb Running Slope(avg)	3.42 ≤ 8.3% ■ > 8.3%		Ramp 1
space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	3.4 ≤ 5.0% ■ > 5.0%	Ramp	Positions Positions
* ² Clear Space area is the width of Ramp Run 1	Det. warning full width of rai		Position	5
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass	Fail	PE Stamp (required for
	Running Slope 2	^{9.4} ≤ 8.3% > 8.3%		private development)
See also Standard Drawings to assess provisions not shown: (inlets, alignment, etc.)	Length 2	8.0		
(linets, ungilinent, etc.)	Cross Slope 2	3.2 ≤ 2.0% > 2.0%		
~ - 4 r	RAMP RUN 3	Pass	Fail	
<i>f T T T T T T T T T T</i>	Running Slope 3	6.1 ≤ 8.3% ■ > 8.3%		
B Run 3	Length 3	7.5		
Fun 2 g	Cross Slope 3	2.1 ≤ 2.0% > 2.0%		
Counter slope	TURN SPACE	Pass	Fail	ts:
	Width X	5 ≥ 4.0' < 4.0'	IITD	
PARALLEL RAMP (PL)	Length Y	5 ≥ 4.0'*1 ■ < 4.0'*	1 🔲 📗	
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	N ≥ 5.0'*1	1 🔲 📗	
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	1.4 ≤ 2.0% ■ > 2.0%		
Detectable Warning Surface Cross Slope (2.0% max.)	Slope Y (Running Slope 1)	3.6 ≤ 2.0% > 2.0%		
Running Slope (8.3% max.)	MISCELLANEOUS	Pass	Fail Inspector's	Signature Date (mm/dd/
Counter Slope (5.0% max.) Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*	Clear Width (feet)	5.0 ≥ 4.0' < 4.0'	Darrell	Wyant 52638
"Il constrained at back of walk, min. T length is 5.	Intersection Control Type	SY Slope of Rd. 1.3	Print name	clearly Certification
Gutter Flow Slope (as directed)	Horizontal Gaps	≤ 1/2" ■ > 1/2"	3J Consult	
	Tiorizontal Gaps	= 1/2	Company/A	Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





