

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

	Conch									
N	w 311	24952.54				Nw C	omm	nercial		
No	rth-South Road Name	Project No. Shee	et No.	No. Intersection No.			East-West Road Name			
		Calibration Date	9/5/2024	(mm/dd,	/yy)			k - ') · · · · · · · · · · · · · · · · ·	. ' .	
	Ramp Style PR	RAMP RUN 1		Pass			Fail	Commen		
	The style in the	Running Slope 1	3.3	≤ 8.3%		>8.3%	Ш	Corner Positions	1	
	ssing value for Gutter Flow Slope (GFS) s on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Length 1	4.5					Position 3	2A	
•		Cross Slope 1	2.2	≤ 2.0%		>2.0%			3	
Signalize	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Υ		N		3A -		
.0%, and at Stop or Yield (SY), GFS must be \leq 2.0%.		Lip Height		1/4"		>1/4"		2 North	2	
If Back of Ramp Obstruction is Yes, turn space		Gutter Flow Slope	1.5	≤ *		>*			1	
ength Y	must be minimum 5.0 ft.	Curb Running Slope (avg)	4.32	≤ 8.3%		>8.3%		Ramp 1		
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	6.2	≤ 5.0%		> 5.0%		Position 5		
	Standard Drawings to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stam private o		
/.	X X X X X X X X X X X X X X X X X X X	Detectable warning extends full width of ramp throat opening		Y		N				
/ * * * * / 5 / * * / * * / * * / * * / * * / * /		TURN SPACE LANDIN	G NOI	NE	Pass		Fail			
	Run 1	Width X	5.0	≥ 4.0'		< 4.0'				
Counter slope Counter slope		Length Y	3.4	≥ 4.0'*1		< 4.0'*1		Comments:		
		Back of Ramp Obstruction (Y/N)		≥ 5.0'*¹		< 5.0'*1				
P	Service AV 1.5 SAV Service 2018 Service 4011 processor 16.0 (8.0 (8.0 (8.0 (8.0 (8.0 (8.0 (8.0 (8	Slope X	0.9	≤2.0%		>2.0%				
⊕	Pedestrian Access Route (to measure Clear Width)	Slope Y	0.7	≤2.0%		>2.0%				
	Detectable Warning Surface	MISCELLANEOUS Traversa	able		Pass		Fail			
	Cross Slope (2.0% max.)	Flare Slope 1	5.9	≤ 10%		< 10%		Inspector's Signature	L Date	
1	Counter Slope (5.0% max.)	Flare Slope 2	8.4	≤ 10%		<10%				
T	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	6.0	≥ 4.0'		< 4.0'		Darrell Wyant Print name clearly	526: Certifi	
-	Gutter Flow Slope (as directed)	Intersection Control Type		Slope of	Road	1.7		3J Consulting	7	
	- de la programma de de la compansa	Horizontal Gaps		≤1/2"		> 1/2"		Company/Agency		
								. ,, ,,		



ADA Curb Ramp Images
Attached photos must be in .pdf format in order to be placed



