WASHINGTON COUNTY OREGON	ADA	A Curb Ramp	New Cons	truction	Inspec	tior	Form (Con	nbination)			
NW 307th Ave		23885.56				٦٢	NW Bartlett Lo	юр				
North-South Road Name		Project No.	Sheet No.	Intersection	on No.		East-West R	oad Na	ame o :		-)
	Calibr	ation Date	7/2/2024	. (mm,	/dd/y	y)		k - U ‡	·) · -			
Ramp Style C		RAMP RUN 1		ass		Fail	1		2.5	2		
* The passing value for Gutter Flow Slope (GFS) depends on the Intersection Condition Type. At a Midblock (MB), GFS must be ≤ Slope of the Road, at		Running Slope 1 Length 1		8.5 ≤ 8.3%			> 8.3%		Corner		Corner	A 100
				3.5					Position	3	Positions	2A 1
				1.5	≤ 2.0%		> 2.0%	\Box		1	0	2
Signalized or Uncontrolled (SU), GFS must be ≤ 5.0%,		Cross Slope 1		1.5	3 2.070			\sqcup				3
and at Stop or Yield (SY), GFS must be 2.0%.		Detectable Warning (Y/N)		Υ	Υ		N		C 04	1	\wedge	
* ¹ If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 feet.		Lip Height		0	≤ 1/4"		> 1/4"		(3A	2	North	2
* ² Clear Space area is the width of Ramp Run 1 and extends 4.0' into the roadway.		Gutter Flow Slop	e	0.3	≤ *		>*			1		
		Curb Running SI	ope _(avg)	5.22	≤ 8.3%		> *8.3%		1	4	Ramp	
See also Standard Drawings to assess provisions not (inlets, alignment, etc.)	Counter Slope (-	-/-)* ²	5.8	≤ 5.0%		> 5.0%		Ramp Position	2	Positions		
Pass	RAMP RUN 2			F	Pass		Fail			PE Stam	o (required for	
1 033	Fail	Running Slope 2		8.8	≤ 8.3%		> 8.3%					levelopment)
Longest distance from detectable warning corner to back of curb (to nearest inch) $< 5.0'$ $\geq 5.0'$		Length 2		5.5								
		Cross Slope 2		1.9	≤ 2.0%		> 2.0%					
Detectable warning extends full width of ramp throat opening Flare Slope Counter slope Counter slope		RAMP RUN 3	Pass Fail									
		Running Slope 3		4.0 ≤ 8.3%			> 8.3%					
		Length 3		4.75								
		Cross Slope 3		2.3	≤ 2.0%		> 2.0%					
		TURN SPACE	Pass			s Fail		Comments:				
		Width X		2.4	≥ 4.0'		< 4.0'		TD			
		Length Y		5.2	≥4.0'* ¹		< 4.0'* ¹					
COMBINATION RAMP (C)		Back of Ramp Ob	N	≥5.0'*1		< 5.0'* ¹						
COMBINATION RAMP (C) Pedestrian Access Route (to measure Clear Width)		Slope X		3.1	≤2.0%		> 2.0%					
		Slope Y		1.1	≤2.0%		> 2.0%					
		MISCELLANEOU	S Traversabl	e	F	Pass		Fail				
Detectable Warning Surface		Flare Slope 1		11.2	≤ 10%		> 10%					
← Cross Slope (2.0% max.) ← Running Slope (8.3% max.)		· ·	=		/ 100/		> 10%	H	Inspector's Signature			Date (mm/dd/yy)
A Counter Slope (5.0% max.)		Flare Slope 2		2.7	≤ 10%			닏ㅣ	Darrell Wyant			52638
Turning Space (X & Y) (2.0% max. / 4' x 4' mi * If constrained at back of walk, min. Y length	n.)* is 5'.	Clear Width (fee	et)	\square	≥ 4.0'		< 4.0'	닖	Print name clearly			Certification No

Gutter Flow Slope (as directed)

Horizontal Gaps (Y/N)

Intersection Control Type

SY


≤ 1/2"

Slope of Road 0.8

1/2"

3J Consulting

Company/Agency



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





