

ADA Curb Ramp New Construction Inspection Form (Perpendicular)

						¬ —		
N	lw 311	24952.54				Nw co	omme	ercial
No	rth-South Road Name	Project No. Shee	et No. In	tersection N	lo.	East-W	est Ro	ad Name
		Calibration Date	9/5/2024	(mm/dd	/yy)			k - ') · · · · · · · · · · · · · · · · ·
	Ramp Style PR	RAMP RUN 1			Pass		Fail	4 Corner
		Running Slope 1	2.5	≤ 8.3%		>8.3%	Ш	Corner Positions
	sing value for Gutter Flow Slope (GFS)	Length 1	4.8					Position 3
•	ls on the Intersection Control Type. At a ck (MB), GFS must be ≤ Slope of the Road, at	Cross Slope 1	1.1	≤ 2.0%		>2.0%		1 3
Signalize	ed or Uncontrolled (SU), GFS must be ≤	Detectable Warning (Y,N)		Y		N		(3A)
5.0% <i>,</i> an	d at Stop or Yield (SY), GFS must be ≤ 2.0%.	Lip Height		1/4"		>1/4"		North
	of Ramp Obstruction is Yes, turn space must be minimum 5.0 ft.	Gutter Flow Slope	0.8	≤ *		>*		
_		Curb Running Slope (avg)	0.72	≤ 8.3%		>8.3%		Ramp Positions
	Space area is the width of Ramp Run 1 and 4.0 ft into the roadway.	Counter Slope (+/-) *2	7.8	≤ 5.0%		> 5.0%		Position 5
	o <u>Standard Drawings</u> to assess provisions not shown: alignment, etc.)	Longest distance from corner to back of curb (see dwg on BT form)		< 5.0'		≥ 5.0'		PE Stamp (require private developm
Counter slope		Detectable warning extends full width of ramp throat opening		Y		N		
		TURN SPACE LANDING	G NON	E	Pass		Fail	
		Width X	5.0	≥ 4.0'		< 4.0'	\Box	
		Length Y	5.5	≥ 4.0'*1		< 4.0'*1		Comments:
		Back of Ramp Obstruction (Y/N)		≥ 5.0' * 1		< 5.0'*1		
PE	Service and the same service service and the service services and the services are serviced as the services and the services are serviced as the service are serviced as the service are serviced as the service are serviced as the serviced as the serviced as the serviced are serviced are serviced as the serviced are serviced as the ser	Slope X	0.5	≤2.0%		>2.0%		
	Pedestrian Access Route (to measure Clear Width)	Slope Y	2.3	≤2.0%		>2.0%		
	Detectable Warning Surface	MISCELLANEOUS Traversa	ble		Pass		Fail	
+	Cross Slope (2.0% max.) Running Slope (8.3% max.)	Flare Slope 1	10.3	≤ 10%		< 10%		Inspector's Signature Date (m
1	Counter Slope (5.0% max.)	Flare Slope 2	7.9	≤ 10%		<10%		
T.	Turning Space (X & Y) (2.0% max. / 4' x 4' min.)* * If constrained at back of walk, min. Y length is 5'.	Clear Width (feet)	5.0	≥ 4.0'		< 4.0'		Darrell Wyant 52638 Print name clearly Certifica
_	Gutter Flow Slope (as directed)	Intersection Control Type	SU	Slope of	Road	0.5		3J Consulting
	accessors political for Vitaliana Care	Horizontal Gaps		· ≤1/2"		> 1/2"		Company/Agency
		<u> </u>				•		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed



