

ADA Curb Ramp New Construction Inspection Form (End of Walk)

Main	24952.54					
North-South Road Name	Project No. Sheet No.	Intersection No. East	West Road		4 1 . 4 - 1	
	Calibration Date	0/8/2024 (mm/dd/yy)			i.gov/odot/Engineering/L ExhibitA.pdf for more coi unty corner numbering s	ner styles.
			E.II		unty corner numbering s	
EW	RAMP RUN 1	Pass	Fail	3	Corner	2
Ramp Style	Running Slope 1	≤ 8.3% ■ >8.3%	· L	Corner Position 3	Positions ,	1
	Length 1	7.1		rosition	5 2	
Use the End of Walk style inspection form	Cross Slope 1	13.9 ≤ 2.0% >2.0%		1	6	3
where sidewalk ends at locations that are not intersections. Turning Space may be measured	Detectable Warning (Y/N) Y N		3A -	1	
at either the top or bottom of the ramp run.				2	North	
	Lip Height	0 1/4" >1/4"		1	/	2
See also Standard Drawings to assess provisions not shown:	Location of Landing in Re	lation		2 4	Ramp 1	
(inlets, alignment, etc.)	to Ramp (top or bottom)			Ramp	Positions	
	Transition Type (tapered	or cont.)	-	Position	5	
	Change of Direction at				PE Stamp (r	•
	End of Walk (Y/N)				private dev	elopment)
	End of Walk Barricade Posted (Y/N)					
C Pun I	TURN SPACE/LANDING	NEITHER Pass	Fail			
ale All All All All All All All All All A	Width X	5.0 ≥ 4.0' ■ < 4.0'				
Total and the sale sale sale sale sale sale sale sal	Length Y	6.0 ≥ 4.0' ■ < 4.0'				
8 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Slope X	5.7 ≤2.0% > 2.0%		Comments:		
To life a age of late me	Slope Y	≤2.0% ■ > 2.0%		IITD gt2		
Tage We will				_		
	MISCELLANEOUS Traversa	able Pass	Fail			
	Flare Slope 1	≤ 10% ■ > 10%				
Pedestrian access route (To measure clear width)	Flare Slope 2	≤ 10% ■ > 10%				
← Cross slope (design to 1.5% max. to achieve 2.0% finish grade)	Clear Width (feet)	5.0 ≥ 4.0' < 4.0		Inspector's Signature		Date .
Running slope (design to 7.5% max to achieve 8.3% finish grade)	Slope of the Road	4.0	_	Darrell Wyant		52638.0
Level area (X & Y) (design to 1.5% max to achieve 2.0% finsh grade / 4' x 4' min.)			. — 1	Print name clearly		Certification No
· Intoligate / + x + Intr./	Horizontal Gaps	≤ 1/2" > 1/2	_	3J Consulting		
			(Company/Agency		



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





