	WASHINGTON COUNTY	
9	OREGON	
	NW Main	
	North-South Road Name	
		PL
		Ramp Sty
dep Mid Roa mus	e passing value for Gutter Flow SI ends on the Intersection Control block (MB), GFS must be \leq Slope d, at Signalized or Uncontrolled (St be \leq 5.0%, and at Stop field (SY), GFS must be \leq 2.0%.	Гуре. At a of the
	f Back of Ramp Obstruction is Yes ce length Y must be minimum 5.0	
* ² (and	Clear Space area is the width of Raextends 4.0 ft into the roadway.	mp Run 1

(inlets, alignment, etc.)

18 Run 3

See also Standard Drawings to assess provisions not shown:

PARALLEL RAMP (PL)

Detectable Warning Surface Cross Slope (2.0% max.) Running Slope (8.3% max.) Counter Slope (5.0% max.)

Gutter Flow Slope (as directed)

PARALLEL RAMP (PL)

Pedestrian Access Route (to measure Clear Width)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)*
* If constrained at back of walk, min. Y length is 5'.

ADA Curb Ramp New Construction Inspection Form (Parallel)

23885.56

Ramp Style

	Project No. Sheet No.	Intersection No.	East-	-West F	Road Name	See https://www.oregor		
	Calibration Date	7/16/2024 (mm	n/dd/yy)				_ExhibitA.pdf for me County corner numb	
1	RAMP RUN 1		Pass	Fail	4	7		2
	Running Slope 1	≤ 2.0%	> 2.0%		Corner		Corner Positions	1
	Cross Slope 1	≤ 2.0%	> 2.0%		Position	3	5	2A 1
	Detectable Warning	Y	■ N		-	1	-	3
	Lip Height	≤ 1/4"	> 1/4"		(3A	\uparrow	
	Gutter Flow Slope	5.3 ≤ *	> *			2	North	2
	Curb Running Slope(avg)	8.1 ≤ 8.3%	= > 8.3%>			4	Pama (1	
	Counter Slope (+/-)*2	^{6.9} ≤ 5.0%	> 5.0%		2 Ramp	2	Ramp 1 Cositions	
	Det. warning full width of ramp	Υ	N		Position		5	
	RAMP RUN 2		Pass	Fail			PE Stamp (r	equired for
	Running Slope 2	11.1 ≤ 8.3%	> 8.3%				private dev	•
	Length 2	7.05						
	Cross Slope 2	≤ 2.0%	> 2.0%					
	RAMP RUN 3		Pass	Fail				
	Running Slope 3	3.6 ≤ 8.3%	■ > 8.3%					
	Length 3	7.2						
	Cross Slope 3	0.8 ≤ 2.0%	= > 2.0%					
	TURN SPACE	1	Pass		Comment			
	Width X	4.9 ≥ 4.0'	■ <4.0'		IIDWS III	D Fails RR 1		
	Length Y	6.1 ≥ 4.0'*1	< 4.0'*1					
	Back of Ramp Obstruction (Y/N)	≥ 5.0'*¹	< 5.0'*1					
	Slope X (Cross Slope 1)	≤ 2.0%	> 2.0%					
	Slope Y (Running Slope 1)	≤ 2.0%	> 2.0%					
MISCELLANEOUS			Pass Fail		Inspector's S	ignature		Date (mm/dd/yy
	Clear Width (feet)	4.9 ≥ 4.0'	< 4.0'		Darrell \			52638
	Intersection Control Type	SY Slope o	of Rd. 5.0		Print name o	•		Certification No
	Horizontal Gaps	0 ≤ 1/2"	> 1/2"		3J Consulti Company/Ag			
					Company/A	KCIICY		

NW Lenox



ADA Curb Ramp Images

Attached photos must be in .pdf format in order to be placed





