WASHINGTON COUNTY OREGON ADA	A Curb Ramp New Constr	uction Inspection Form (Par	allel)
311th	24952.54	Claxter	
North-South Road Name	Project No. Sheet No.	Intersection No. East-West	Road Name See https://www.oregon.gov/odot/Engineering/Documents
	Calibration Date	9/20/2024 (mm/dd/yy)	_RoadwayEng/ADA_ExhibitA.pdf for more corner styles Use Washington County corner numbering system.
PL	RAMP RUN 1	Pass Fail	3
Ramp Style	Running Slope 1	≤ 2.0% > 2.0%	Corner
*The passing value for Gutter Flow Slope (GFS)	Cross Slope 1	≤ 2.0% > 2.0%	Position 3
depends on the Intersection Control Type. At a	Detectable Warning	Y Y N	
Midblock (MB), GFS must be ≤ Slope of the Road, at Signalized or Uncontrolled (SU), GFS	Lip Height	0 ≤ 1/4" ■ > 1/4"	3A -
must be ≤ 5.0%, and at Stop	Gutter Flow Slope	2.5 ≤ * > *	North
or Yield (SY), GFS must be ≤ 2.0%.	Curb Running Slope(avg)	6.58 ≤ 8.3% ■ > 8.3%>	
*1 If Back of Ramp Obstruction is Yes, turn space length Y must be minimum 5.0 ft.	Counter Slope (+/-)*2	<u>5.4</u> ≤ 5.0%  >  5.0%  ■	1 Positions 1 Positions
*2 Clear Space area is the width of Ramp Run 1	Det. warning full width of ramp	Y Y N	Ramp Position
and extends 4.0 ft into the roadway.	RAMP RUN 2	Pass Fail	PE Stamp (required for
	Running Slope 2	≤ 8.3%  > 8.3%	private development)
See also Standard Drawings to assess provisions not shown:	Length 2	9.25	
(inlets, alignment, etc.)	Cross Slope 2	3.6 ≤ 2.0%  > 2.0%	
Counter slope  Counter slope  Counter slope	RAMP RUN 3	Pass Fail	
	Running Slope 3	≤ 8.3% > 8.3%	
	Length 3	7.3	
	Cross Slope 3	3.3 ≤ 2.0%  > 2.0%  ■	- Comments:
	TURN SPACE	Pass Fail	
	Width X	4.85 ≥ 4.0' < 4.0'	IITD, gt2. BOR drop off.
PARALLEL RAMP (PL)	Length Y	5.0 ≥ 4.0'*1 <b>■</b> < 4.0'*1	
PARALLEL RAMP (PL)	Back of Ramp Obstruction (Y/N)	Y ≥ 5.0'*1 < 5.0'*1	
Pedestrian Access Route (to measure Clear Width)	Slope X (Cross Slope 1)	≤ 2.0% > 2.0%	

**Detectable Warning Surface** 

Cross Slope (2.0% max.)

Running Slope (8.3% max.)

Counter Slope (5.0% max.)

Turning Space (X & Y) (2.0% max. / 4' x 4' min.)\*
\* If constrained at back of walk, min. Y length is 5'.

Gutter Flow Slope (as directed)

Slope Y (Running Slope 1)

**MISCELLANEOUS** 

Clear Width (feet)

**Horizontal Gaps** 

Intersection Control Type

> 2.0%

< 4.0'

Pass

≤ 1/2" ■ > 1/2"

Fail Inspector's Signature

Darrell Wyant

Print name clearly

Company/Agency

3J Consulting

≤ 2.0%

≥ 4.0'

Slope of Rd.

4.85

SY

Date (mm/dd/yy)

Certification No.

52638



## **ADA Curb Ramp Images**

Attached photos must be in .pdf format in order to be placed





